














<p>Violation #: 1</p> 	<p>Silkscreen over Mask                  May make electrical testing &amp; SMT soldering more difficult.</p> <p>Layers Involved: Sst0126.pho, Sm0128.pho                  Approximate Location (mil): ( 19041.134, 16337.465 )</p>
<p>Violation #: 2</p> 	<p>Silkscreen over Mask                  May make electrical testing &amp; SMT soldering more difficult.</p> <p>Layers Involved: Sst0126.pho, Sm0128.pho                  Approximate Location (mil): ( 17501.193, 18015.496 )</p>
<p>Violation #: 3</p> 	<p>Silkscreen over Mask                  May make electrical testing &amp; SMT soldering more difficult.</p> <p>Layers Involved: Sst0126.pho, Sm0128.pho                  Approximate Location (mil): ( 20006.803, 17968.154 )</p>
<p>Violation #: 4</p> 	<p>Silkscreen over Mask                  May make electrical testing &amp; SMT soldering more difficult.</p> <p>Layers Involved: Sst0126.pho, Sm0128.pho                  Approximate Location (mil): ( 20091.283, 17926.335 )</p>
<p>Violation #: 5</p> 	<p>Silkscreen over Mask                  May make electrical testing &amp; SMT soldering more difficult.</p> <p>Layers Involved: Sst0126.pho, Sm0128.pho                  Approximate Location (mil): ( 22364.150, 18531.890 )</p>
<p>Violation #: 6</p> 	<p>Mask Clearance too small                  May not keep mask off pads.</p> <p>Layers Involved: Sm0227.pho, Art02.pho                  Approximate Location (mil): ( 16677.102, 18163.882 )</p>

<p>Violation #: 7</p> 	<p>Mask Clearance too small                  May not keep mask off pads.</p> <p>Layers Involved: Sm0227.pho, Art02.pho                  Approximate Location (mil): ( 16488.488, 18239.996 )</p>
<p>Violation #: 8</p> 	<p>Mask Clearance too small                  May not keep mask off pads.</p> <p>Layers Involved: Sm0128.pho, Art0121.pho                  Approximate Location (mil): ( 16677.102, 18163.882 )</p>
<p>Violation #: 9</p> 	<p>Mask Clearance too small                  May not keep mask off pads.</p> <p>Layers Involved: Sm0128.pho, Art0121.pho                  Approximate Location (mil): ( 16488.488, 18239.996 )</p>
<p>Violation #: 10</p> 	<p>Plane Annular Ring                  May cause registration problems or shorts during manufacturing.</p> <p>Layers Involved: gnd2530.pho, Drill.drl                  Approximate Location (mil): ( 19272.146, 13992.437 )</p>
<p>Violation #: 11</p> 	<p>Plane Annular Ring                  May cause registration problems or shorts during manufacturing.</p> <p>Layers Involved: gnd2530.pho, Drill.drl                  Approximate Location (mil): ( 16519.425, 18222.346 )</p>
<p>Violation #: 12</p> 	<p>Plane Annular Ring                  May cause registration problems or shorts during manufacturing.</p> <p>Layers Involved: gnd2530.pho, Drill.drl                  Approximate Location (mil): ( 18436.106, 13096.854 )</p>

<p>Violation #: 13</p> 	<p>Plane Annular Ring May cause registration problems or shorts during manufacturing.</p> <p>Layers Involved: gnd2530.pho, Drill.drl Approximate Location (mil): ( 18236.106, 13096.854 )</p>